

## **Sport Aviation Corp Ltd**

## Microlight Aircraft Defect Report

		0.
Reporter's Name: Address:	Crack found in engine crankcase	
Aircraft Registratio		
Microlight Type: TECNAM Model: BRAUD P. 2004		
Total Time in Service: - Airframe: 857 Hours Engine: 857 Hours		
Hours Since last inspection: 83. Report date: 27/2/2013.		
Reporter:	Owner Inspector Safety Officer Other	l
Defect Type:	Airframe Engine Instruments Other Circle One	
Location if Airframe:	Fuselage Wings Tail Other	
Discovered During:	Preflight Inspection Maintenance Flight Other	
Describe the defect in detail (attach photos if possible): A CRACK WAS DISOURRED ON THE CRANKCASIZ ADTACIZNT TO NOZ CYLINDRR.  THIS IS A KNOWN ROTTAX 912 ULS PROBLEM AS  THIS HLIGHTED IN SB912-029		
Describe the effects (if any) of the defect on airworthiness:  AIRCRAFT IS UNSERVICIZABLE FOR FURTHER FLIGHT		
Describe remedial action taken and by whom: AIRCRAFT IS CURRENTLY GROUNDIED		
TOTAL ENGINE REPLACEMENT IS CHRIED DUT		
ENGINE BER: ENGINE REPLACED WITH NEW ITEM.		

X

Sport Aviation Corp Ltd Operations Manual

Revision 0 20 Apr 1998

Form # 8.9