

Engine Failure on test flight



Sport Aviation Corp Ltd

Problem Report

Report No
SAC use only

PROBLEM: (What, where, when etc.)

Engine failed after Take off at Pukekohe Airfield 1400 11 06 17 in Microlight First Flight of a new Aircraft. No other option except return to land. Successful, but overran runway hitting end fence 20KTS. Aircraft damaged, PIC Injured. Date/time: 11 / 06 / 17

REPAIRS: TBA. Aircraft owner will fix with help from LAME

Who is to fix it? (Owner):

PROBLEM WAS FIXED: No. Troubleshoot required. By owner.

Name of person responsible:

Date/time: / / :

USE OF THE PROBLEM WAS: UNKNOWN at this time

ACTION REQUIRED TO STOP RECURRENCE: Aircraft will not be flown after repair until reason for engine failure found.

ANY SYSTEMS TO BE IMPROVED?: TBA.

IMPROVEMENT WAS MADE: TBA.

FOR USE ONLY

Corrective Action taken: Signed: _____ Date/time: / / :

Signature: _____

Circle Status: PENDING or CLOSED